

AMPFIELD RECREATION GROUND Playground Inspection No. 2020 / 04

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	✓			
Floor surface	✓			
Signs	✓			
Gates	✓			
Fences	✓			
Benches	✓			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
2 x Cradle Swings	✓			
2x Flat Swings	✓			
Stepping Pods	✓			
Spinning Pole	✓			
Two Up One down slide unit	✓			
See-Saw	✓			
Springers (2)	✓			
Inclusive rotating dish	✓			
Super Rope – End Swinger Mini	✓			

Date 23/02/2020..... **Time Completed**12.15pm.....








Weather Conditions: Raining

Additional Observations

Signature Name David Stevens


Signature Name

AMPFIELD RECREATION GROUND INSPECTION No. 2020 / 04

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances				
Pavilion Inc fire extinguishers				
Sewerage Plant (Listen and warning light)				
Container				
Outfield				
Site Boundaries, Fences and Hedges				
Bins		Pavilion end bin – empty Car Park end bin – nearly empty.		

Weather Conditions: Raining

Additional Observations

Signature  Name ...David Stevens.....

Signature Name

Date