

AMPFIELD RECREATION GROUND Playground Inspection No. 2020 / 40

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	✓			
Floor surface	✓			
Signs	✓			
Gates	✓			
Fences	✓			
Benches	✓			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	✓			
Multi Play	✓			
Roundabout	✓			
Spring See-Saw	✓			
2Bay Swing	✓			

Date ...01/12/2020..... **Time Completed** ...11.45am.....

Weather Conditions: Bright & cold

Additional Observations

Signature NameBryan Nanson....

Signature Name

AMPFIELD RECREATION GROUND INSPECTION No. 2020 / 40

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	✓			
Pavilion Inc fire extinguishers	✓			
Sewerage Plant (Listen and warning light)	✓			
Container	✓			
Outfield	✓			
Site Boundaries, Fences and Hedges	✓			
Bins	✓			

Weather Conditions

Bright &, cold

Additional Observations

Signature Name ...Bryan Nanson.....

Signature Name

Date ...01/12/2020.....