AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General	ОК			
Environment				
Floor surface	ОК			
Signs	ОК			
Gates	ОК			
Fences	ОК			
Benches	ОК			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	OK			
Multi Play	OK			
Roundabout	OK			
Spring See-Saw	ОК			
2Bay Swing	ОК			

Date	1//05/202	2	Time Coi	mplete	d 17:15
Weathe	r Conditions	cloud, dry			
Additio	nal Observati	ons			
Signatu	re			Name	G Roads
Signatuı	re			Name	

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	ОК	Issues	Risk	Time Scale
	?		L/M/H	
Entrances	OK			
Pavilion Inc fire extinguishers	OK			
Sewerage Plant (Listen and warning light)	OK			
Container	ОК	Graffiti on container sides that we know about already	L	
Outfield	ОК	Some litter. Cricketers were on site preparing the ground for a match. Will check today and clear up if necessary.		
Site Boundaries, Fences and Hedges	OK			
Bins	OK	Need emptying		

W	/eath	er Con	ditions	Cloud	d, c	lry
---	-------	--------	---------	-------	------	-----

Additional Observations

Signature	Nam	neG Roads
Signature	Nam	ne
Date 17/05//2022		