## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary	0//2	laura	Risk	Time Scale
Items	OK?	Issues	L/M/H	
General Environment	$\checkmark$			
Floor surface	$\checkmark$			
Signs	$\checkmark$			
Gates	$\checkmark$			
Fences	$\checkmark$			
Benches	$\checkmark$			
Equipment	OK?	lssues	Risk L/M/H	Time Scale
Turnstile	$\checkmark$			
Multi Play	$\checkmark$			
Roundabout	$\checkmark$			
Spring See-Saw	$\checkmark$			
2Bay Swing	$\checkmark$			

Date 22/06/2021..... Time Completed ...19.15.....

Weather Conditions: Cloudy

Additional Observations

Signature	NameDavid Stevens
Signature	Name

(Version 1.0 Issued 20/12/2020)

## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	ОК ?	Issues	Risk L/M/H	Time Scale
Entrances	$\checkmark$			
Pavilion Inc fire extinguishers	$\checkmark$			
Sewerage Plant (Listen and warning light)				
Container	<			
Outfield				
Site Boundaries, Fences and Hedges	$\checkmark$			
Bins	$\checkmark$	Car park 1/4 full White Horse full	Μ	

Weather Conditions: Fair

## **Additional Observations**

Portacabin found to be unlocked.

Signature ..... Name .....

Date ...22/06/2021.....

(Version 1.0 Issued 20/12/2020)