AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General Environment				
Liviroinnent				
Floor surface				
	~			
Signs				
	~			
Gates				
	~			
Fences				
	~			
Benches				
	~			
			Risk	Time Scale
Equipment	OK?	Issues	L/M/H	
Turnstile				
	~			
Multi Play				
Widiti Flay				
Roundabout	~			
Spring See-Saw	~			
2D C '				
2Bay Swing	~			

Date	05/09/2021 Tim	e Completed11.30
Weathe	r Conditions Sunny	
Additio	nal Observations	
Signatu	re	NameDoreen Matthews
Signatu	re	Name

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	ОК	Issues	Risk	Time Scale
	?		L/M/H	
Entrances				
	~			
Pavilion				
Inc fire extinguishers	~			
Sewerage Plant				
(Listen and warning				
light)				
Container				
	~			
Outfield				
	~			
Site Boundaries,				
Fences and Hedges	~			
Bins				
	*			

Weather Conditions Sunn

Additional Observations

Signature		Name	Doreen Matthews
Signature		Name	
Date	05/09/2021		