AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General	OK			
Environment				
Floor surface	OK			
Signs	ОК			
Gates	ОК			
Fences	ОК			
Benches	ОК			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Equipment	OK OK	133463		
Turnstile				
	ОК			
Multi Play				
Roundabout	ОК			
	ОК			
Spring See-Saw				
2Pay Swing	ОК			
2Bay Swing				

Date	07/03/2023	. Time Complete	d 09:00				
Weather Conditions Damp, cloudy							
Additional Observations							
Signature		Name	G Roads				
Signature		Name					

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	ОК	Issues	Risk	Time Scale
	?		L/M/H	
Entrances	Ok			
	OK			
Pavilion				
Inc fire extinguishers	OK			
Sewerage Plant				
(Listen and warning	OK			
light)				
Container	Ol.			
	Ok			
Outfield				
	ОК			
Site Boundaries,				
Fences and Hedges	OK			
D:				
Bins	ОК			
	UK			

Weather Conditions	damı	o cloudy
---------------------------	------	----------

Additional Observations

Signatur	e		 Name	G Roads
Signatur	e		 Name	
Date	0	7/03/2023.		