

AMPFIELD RECREATION GROUND Playground Inspection No. 2020 / 38

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	✓			
Floor surface	✓			
Signs	✓			
Gates	✓			
Fences	✓	Small (250mm?) section of fencing next to white painted building come away from main fence	L	6 months
Benches	✓			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	✓			
Multi Play	✓			
Roundabout	✓			
Spring See-Saw	✓			
2Bay Swing	✓			

Date 02/11/2020 **Time Completed** 11:00

Weather Conditions Dry and sunny

Additional Observations

Signature C J Ling

Name C J LING

AMPFIELD RECREATION GROUND INSPECTION

No. 2020 / 38

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	✓			
Pavilion Inc fire extinguishers	✓	Three lights in entrance to, and toilet of, away changing room flicker.	L	6 months
Sewerage Plant (Listen and warning light)	✓			
Container	✓			
Outfield	✓			
Site Boundaries, Fences and Hedges	✓			
Bins	✓			

Weather Conditions

Sunny and dry

Additional Observations

Signature C J Ling

Name C J LING

Date 02/11/2020