AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General				
Environment				
Floor surface				
Signs	/			
Gates	V			
Fences	V			
Benches	V			
Faurinanant	OK?	lanca.	Risk	Time Scale
Equipment	4	Issues	L/M/H	
Turnstile				
Multi Play	•			
Roundabout	•			
Spring See-Saw	•			
2Bay Swing				

Date	24/12/2022	Time Completed	11.0	00		
Weather Conditions - Cloudy and dull						
Additional Observations						
Signatur	e[) Matthews	Name			
Signatur	e		Name			

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	•			
Pavilion Inc fire extinguishers	•			
Defibrillator – solid icons displayed	•			
Sewerage Plant (Listen and warning light)	V			
Container	•			
Outfield	•			
Site Boundaries, Fences and Hedges	•			
Bins	•			

Weather	Conditions	Dull	Wet ur	nderfoot

Additional Observations

Signature	D Matthews	Name	
Signature		Name	
Date24/12	./2022		