## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General	<b>V</b>			
Environment				
Floor surface	•			
Signs	<b>V</b>			
Gates	<b>V</b>			
Fences	<b>V</b>			
Benches	<b>V</b>			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	<b>~</b>			
Multi Play	<b>V</b>			
Roundabout	•			
Spring See-Saw	<b>V</b>			
2Bay Swing	<b>V</b>			

Date	14/03/2024	Time Complete	d1030
Weather C	onditions. Light rain, a	and wet underfoo	t
Additional	Observations		
Signature	B Nanson	Name	
Signature		Name	

## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	<b>V</b>			
Pavilion Inc fire extinguishers	<b>V</b>			
Defibrillator – solid icons displayed	<b>V</b>			
CCTV Cameras - free from cobwebs	•			
Sewerage Plant (Listen and warning light)	<b>~</b>			
Container	<b>~</b>			
Outfield	<b>~</b>			
Site Boundaries, Fences and Hedges	<b>V</b>			
Bins				

Weather Conditions. Light rain, and wet underfoo	Weather Cond	l <b>itions.</b> Light	rain, and	l wet und	derfoo
--	--------------	------------------------	-----------	-----------	--------

## **Additional Observations**

Signature	B Nanson	Name	
Signature		Name	
J		runic	
Date14/0	03/2024		