AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General	V			
Environment				
Floor surface	•			
Signs	V			
Gates	V			
Fences	V			
Benches	V			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	~			
Multi Play	V			
Roundabout	•			
Spring See-Saw	V			
2Bay Swing	V			

Date	08/10/2023	Time Complete	d 1115
Weathe	r Conditions. Sunny		
Additio	nal Observations		
Signatu	reB Nanson	Name	
Signatu	·e	Name	

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	/			
Pavilion Inc fire extinguishers	•			
Defibrillator – solid icons displayed	•			
CCTV Cameras - free from cobwebs	•			
Sewerage Plant (Listen and warning light)	•			
Container	•			
Outfield	•			
Site Boundaries, Fences and Hedges	•			
Bins	•	Bin at main entrance not emptied – reported to TVBC.		

Weather Conditions. Sunny	Weather	Conditions.	Sunny
---------------------------	---------	-------------	-------

Additional Observations

Signature	B Nanson	Name	
_			
Signature		Name	
Date08/	10/2023		