

AMPFIELD RECREATION GROUND Playground Inspection No. 2020 / 32

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	✓			
Floor surface	✓			
Signs	✓			
Gates	✓			
Fences	✓			
Benches	✓			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	✓			
Multi Play	✓			
Roundabout	✓			
Spring See-Saw	✓			
2Bay Swing	✓			

Date ...20/09/2020..... **Time Completed** ...10.30am.....





Weather Conditions: Bright, dry, breezy

Additional Observations

Signature NameBryan Nanson....

Signature Name

AMPFIELD RECREATION GROUND INSPECTION No. 2020 / 32

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances				
Pavilion Inc fire extinguishers				
Sewerage Plant (Listen and warning light)				
Container				
Outfield				
Site Boundaries, Fences and Hedges				
Bins		Both general purpose bins empty. Recycle bin full		

Weather Conditions

Bright, dry, breezy

Additional Observations

Signature Name ...Bryan Nanson.....

Signature Name

Date ...20/09/2020.....