AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General Environment	✓			
Floor surface	✓			
Signs	✓			
Gates	✓			
Fences	√			
Benches	✓			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	✓			
Multi Play	✓			
Roundabout	✓			
Spring See-Saw	✓			
2Bay Swing	√			

Date	10th September 2023	Time Completed	14:40am
------	---------------------	----------------	---------

Weather Conditions Overcast, warm

Additional Observations

Signature CJ Ling Name CJ Ling

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	✓			
Pavilion Inc fire extinguishers	✓			
Defibrillator – solid icons displayed	√			
Sewerage Plant (Listen and warning light)	√			
Container	√			
Outfield	√			
Site Boundaries, Fences and Hedges	✓			
Bins	√			

Weather Cond	itions	Overcast, warm	1
Additional Obs	ervations		
Signature	C J Ling	Name	C J Ling

Date 10th September 2023

Weather Conditions