AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General	1			
Environment				
Floor surface	/			
Signs	•			
Gates	•			
Fences	•			
Benches	/			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Equipment	_	issues	L/ IVI/ II	
Turnstile				
Multi Play	V			
Roundabout	V			
Spring See-Saw	V			
2Bay Swing	V			

Date	09/01/2022Time Complete	d 10.3	30			
Weather Conditions cold, sunny,						
Additional Observations						
Signatu	eD Matthews	Name				
Signatu	e	Name				

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	•		L/IVI/H	
Pavilion Inc fire extinguishers	V			
Defibrillator – solid icons displayed	V			
Sewerage Plant (Listen and warning light)	•			
Container	V			
Outfield	V			
Site Boundaries, Fences and Hedges	V			
Bins	V			

Weather Conditions	cold	cunny	wat ur	derfoot
weather Conditions	(0)	Summv.	. wei ui	10001

Additional Observations

Signature	D Matthews	Name	
Signature		Name	
Date 09/01	/2022		