AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General	/			
Environment	Y			
Floor surface	\checkmark			
Signs	✓			
Gates	✓			
Fences	✓			
Benches	✓			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	✓			
Multi Play	√			
Roundabout	√			
Spring See-Saw	√			
2Bay Swing	✓			

Date 13th October 2025 Time Completed 3:40pm

Weather Conditions Dry, Overcast

Additional Observations

Signature C J Ling Name C J Ling

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	√			
Pavilion Inc fire extinguishers	✓			
Defibrillator – solid icons displayed	✓			
Sewerage Plant (Listen and warning light)	✓			
Container	✓			
Outfield	✓			
Site Boundaries, Fences and Hedges	✓			
Bins	✓			

Weather Conditi	ions	Dry, Overcast							
Additional Observations									
Signature	C J Ling	Name	C J Ling						

Date 13th October 2025