

**AMPFIELD RECREATION GROUND Playground Inspection No. 2020 / 23**

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	✓			
Floor surface	✓			
Signs	✓			
Gates	✓			
Fences	✓			
Benches	✓			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	✓			
Multi Play	✓			
Roundabout	✓			
Spring See-Saw	✓			
2Bay Swing	✓			

**Date** ...20 July 2020 .... **Time Completed** ...11.00.....

**Weather Conditions** Bright & dry

**Additional Observations**

Signature ..... Name ...Bryan Nanson.....

Signature ..... Name .....

**AMPFIELD RECREATION GROUND INSPECTION** No. 2020 / 23

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	✓			
Pavilion Inc fire extinguishers	✓			
Sewerage Plant (Listen and warning light)	✓			
Container	✓			
Outfield	✓			
Site Boundaries, Fences and Hedges	✓			
Bins	<b>X</b>	The bin at the vehicle entrance was full to overflowing with dog poo bags being placed on top. Reported to TVBC 20/07/2020	L	3 days

**Weather Conditions**    **Bright & dry**

**Additional Observations**

Signature ..... Name ...Bryan Nanson.....

Signature ..... Name .....

**Date** .....20/07/2020.....