AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General	ОК			
Environment				
Floor surface	ОК			
Signs	OK			
Gates	ОК			
Fences	ОК			
Benches	ОК			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	OK			
Multi Play	OK			
Roundabout	OK			
Spring See-Saw	OK			
2Bay Swing	OK			

Date	31/10/21	Time Completed 12:00 pm							
Weather Conditions sun showers windy									
Additional Observations									
Signatuı	re	NameG Roads							
Signatuu	*A	Name							

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	ОК	Issues	Risk	Time Scale
	?		L/M/H	
Entrances	OK			
Pavilion Inc fire extinguishers	OK			
Sewerage Plant (Listen and warning light)	OK	Noise, no light		
Container	OK			
Outfield	OK			
Site Boundaries, Fences and Hedges	OK			
Bins				

ons								
Sun showers windy								
Additional Observations								
	N	Name	G Roads					
	N	lame						
2021								
	rvations	ndy rvations	ndy rvations Name Name					