AMPFIELD RECREATION GROUND Playground Inspection No. 2020 / 02

Auxiliary			Risk	Time Scale
Items	ок?	Issues	L/M/H	
General	V			
Environment				
Floor surface				
Signs	V			
Gates	V			
Fences	V			
Benches	V			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
2 x Cradle Swings	V			
2x Flat Swings	V			
Stepping Pods	V			
Spinning Pole	V			
Two Up One down slide unit	V			
See-Saw	V			
Springers (2)	V			
Inclusive rotating dish	~			
Super Rope – End Swinger Mini	V			

Date	26/0	1/2020	Time Co	mpiete	a 1045	
Weather Conditions: Overcast						
Additional Observations						
Signatu	re			Name	Bryan Nanson	
Signatu	re			Name		

1

^{*}Inspection number to be added by Inspector

AMPFIELD RECREATION GROUND INSPECTION No. 2020 / 02

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	•			
Pavilion Inc fire extinguishers	V			
Sewerage Plant (Listen and warning light)	•			
Container	~			
Outfield	~			
Site Boundaries, Fences and Hedges	~			
Bins	•			

۱۸	laathar	Conditions	Overcast
W	/eatner	Conditions	Overcasi

Additional Observations

Signature		Name	Bryan Nanson
Signature		Name	
Date 26	/01/2020		