

## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	✓			
Floor surface	✓			
Signs	✓			
Gates	✓			
Fences	✓			
Benches	✓			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	✓			
Multi Play	✓			
Roundabout	✓			
Spring See-Saw	✓			
2Bay Swing	✓			

**Date** ...28/11/2021..... **Time Completed** ...11.30.

**Weather Conditions** Cold & bright

**Additional Observations**

Signature ..... Name ...Bryan Nanson.....

Signature ..... Name .....

## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	✓			
Pavilion Inc fire extinguishers	X	Electricity had tripped out. Unit reset leaving the offending circuit, i.e. external lighting, off. Electrician notified and asked to remedy.	L	2 – 3 weeks
Defibrillator – solid icons displayed	✓			
Sewerage Plant (Listen and warning light)	✓			
Container	✓			
Outfield	✓			
Site Boundaries, Fences and Hedges	✓			
Bins	✓			

**Weather Conditions** Cold & bright

### Additional Observations

Signature ..... Name ..... Bryan Nanson .....

Signature ..... Name .....

**Date** .....28/11/2021.....