AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General	\checkmark			
Environment				
Floor surface	\checkmark			
Signs	\checkmark			
Gates	\checkmark			
Fences	\checkmark			
Benches	\checkmark			
Facility	01/2		Risk	Time Scale
Equipment	OK?	lssues	L/M/H	
Turnstile				
Multi Play	✓			
Roundabout	\checkmark			
Spring See-Saw	\checkmark			
2Bay Swing	 ✓ 			

Date 7rd August 2023 Time Completed 12:00am

Weather Conditions Overcast, warm, dry

Additional Observations

Signature CJLing Name CJLing

(Version 1.1 Issued 07/11/2021)

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	\checkmark			
Pavilion Inc fire extinguishers	\checkmark			
Defibrillator – solid icons displayed	\checkmark			
Sewerage Plant (Listen and warning light)	√			
Container	\checkmark			
Outfield	\checkmark			
Site Boundaries, Fences and Hedges	\checkmark			
Bins	\checkmark			

Weather Conditions Overcast, warm, dry

Additional Observations

Signature CJLing Name CJLing

Date 7th August 2023

(Version 1.1 Issued 07/11/2021)