## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General Environment				
Liviroinnent				
Floor surface				
	<b>~</b>			
Signs				
	<b>~</b>			
Gates				
	<b>~</b>			
Fences				
	<b>~</b>			
Benches				
	<b>~</b>			
			Risk	Time Scale
Equipment	OK?	Issues	L/M/H	
Turnstile				
	~			
Multi Play				
Widiti Flay				
Roundabout	~			
Spring See-Saw	<b>~</b>			
2D C '				
2Bay Swing	<b>~</b>			

Date	11/07/2021	Time Complete	<b>d</b> 11.00		
Weather Conditions Cool & dull					
Additional Observations					
Signatu	re	Name	Doreen Matthews		
Signatu	re	Name	1		

## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	ОК	Issues	Risk	Time Scale
	?		L/M/H	
Entrances				
	<b>~</b>			
Pavilion				
Inc fire extinguishers	<b>~</b>			
Sewerage Plant				
(Listen and warning				
light)				
Container				
	<b>~</b>			
Outfield				
Site Boundaries,				
Fences and Hedges				
Bins				

14/46	C =	C10	ال الم
weather	Conditions	COOL	aun

## **Additional Observations**

Signature		Name	Doreen Matthews
Signature		Name	
Date11/0	07/2021		